



## Special Notice 19-25

**\*\*\*URGENT\*\*\***

**Date:** 7 May 2019  
**Subject:** Incorrect Procedure Turn Course  
Sioux City, Iowa  
Sioux Gateway/Col Bud Day Field (KSUX)  
ILS or LOC RWY 13  
Cycle 1905, 1906

The procedures have an incorrect outbound course for the procedure turn.

<b>Airport</b>	<b>Procedures</b>	<b>Error</b>
KSUX	I13 & L13	The procedure turn was coded with an incorrect outbound course. The correct course should be 268 degrees.

AeroNavData advises to use the procedure with extreme caution until an updated data delivery is made. The data will be updated to reflect the latest source in the cycle 1907 data effective Thursday, June 20, 2019.

**Special notices are disseminated to notify customers of issues with navigational data which may affect flight operations or safety. Information contained herein should be immediately relayed to appropriate personnel!**

**Important: Check NOTAMs and other pertinent information prior to flight.**

All questions regarding this Special Notice should be addressed to:

Email: [production@aeronavdata.com](mailto:production@aeronavdata.com)

Phone: 618-281-8986

Fax: 618-281-8558

1839 Ghent Rd.  
Columbia, IL 62236

CC#

Form CC# 2211001011