

Airbus, Boeing or McDonnell Douglas aircraft upgrade path

GPS Position Source

<u>Current Supplier</u>	<u>Current Equipment Type</u>	<u>Future Supplier</u>	<u>Future Equipment Type</u>	<u>Upgrade Path</u>
Rockwell Collins	GLU-925	N/A	N/A	Compliant
Rockwell Collins	GLU-920 (822-1152-003 or lower)	Rockwell Collins	GLU-920 (822-1152-004/005)	Service Bulletin Upgrade
Rockwell Collins	GPS-4000S	N/A	N/A	Compliant
Rockwell Collins	GPS-4000A	Rockwell Collins	GPS-4000S	Service Bulletin Upgrade
Rockwell Collins	GPS-4000	Rockwell Collins	GPS-4000S	New Hardware Purchase
Honeywell	RMA-55B	Rockwell Collins	GLU-925	New Hardware Purchase
Other Standalone GPS	Various	Rockwell Collins	GPS-4000S	New Hardware Purchase
No GPS Installed	N/A	Rockwell Collins	GPS-4000S	New Hardware Purchase

DO-260B Transponder

<u>Current Supplier</u>	<u>Current Equipment Type</u>	<u>Future Supplier</u>	<u>Future Equipment Type</u>	<u>Upgrade Path</u>
Rockwell Collins	TPR-901 (822-1338-2X5)	N/A	N/A	Compliant
Rockwell Collins	TPR-901 (822-1338-021 or lower)	Rockwell Collins	TPR-901 (822-1338-2X5)	Service Bulletin Upgrade
Rockwell Collins	TPR-900	Rockwell Collins	TPR-901 (822-1338-2X5)	New Hardware Purchase
Rockwell Collins	TPR-720	Rockwell Collins	TPR-901 (822-1338-2X5)	New Hardware Purchase
Honeywell	TRA-67A	Rockwell Collins	TPR-901 (822-1338-2X5)	New Hardware Purchase

**Rockwell
Collins**

Building trust every day