

Regional and Business aircraft upgrade path

GPS Position Source

<u>Current Supplier</u>	<u>Current Equipment Type</u>	<u>Future Supplier</u>	<u>Future Equipment Type</u>	<u>Upgrade Path</u>
Rockwell Collins	GPS-4000S	N/A	N/A	Compliant
Rockwell Collins	GPS-4000A	Rockwell Collins	GPS-4000S	Service Bulletin Upgrade
Rockwell Collins	GPS-4000	Rockwell Collins	GPS-4000S	New Hardware Purchase
No GPS Installed	N/A	Rockwell Collins	GPS-4000S	New Hardware Purchase

DO-260B Transponder

<u>Current Supplier</u>	<u>Current Equipment Type</u>	<u>Future Supplier</u>	<u>Future Equipment Type*</u>	<u>Upgrade Path</u>
Rockwell Collins	TDR-94D (622-9210-501)	N/A	N/A	Compliant
Rockwell Collins	TDR-94 (622-9352-501)	N/A	N/A	Compliant
Rockwell Collins	TDR-94D (622-9210-006 or lower)	Rockwell Collins	TDR-94D (622-9210-501)	New Hardware Purchase
Rockwell Collins	TDR-94D (622-9210-007 or higher)	Rockwell Collins	TDR-94D (622-9210-501)	Service Bulletin Upgrade
Rockwell Collins	TDR-94 (622-9352-006 or lower)	Rockwell Collins	TDR-94 (622-9352-501)	New Hardware Purchase
Rockwell Collins	TDR-94 (622-9352-007 or higher)	Rockwell Collins	TDR-94 (622-9352-501)	Service Bulletin Upgrade
Rockwell Collins	TDR-90 (All)	Rockwell Collins	TDR-94/94D (622-9XXX-501)	New Hardware Purchase
Honeywell	MST-67A	Rockwell Collins	TDR-94D (622-9210-501)	New Hardware Purchase

*For aircraft operating in areas that only require DO-260A, the TDR-94/94D (622-9XXX-409) are sufficient