

Navigation Database Addendum

Correction to AIRAC 1906 – Issue 6

AIRAC AMDT 01/19 effective 23rd May 2019

HAAA FIR

Due to late reception of document, following data not updated:

AWY UB525 deleted

AWY **UG657** renamed to UM310

AWY UM997: WPT IMTED N10 33.8 E042 27.5 between ASTAR and DWA missing

AWY UN304: WPT SETIT deleted, WPT UDLAX N08 38.2 E042 19.1 between DWA and EPTOV missing

AWY UT667: WPT UVKAS N09 28.3 E040 44.9 between MIWAS and DWA missing

AWY W15: WPT NETIN N05 18.0 E040 00.0 between UTANO and IMKIT missing

AWY W885: WPT TILOK N09 34.6 E042 57.6 between DWA and ARSHI missing

Airport HAAX: All STARs are not updated and should not be used.

Following procedures are missing in the database:

Airport HAAM: APCH RNAV (GNSS) RWY 03

Airport HALL: APCH RNAV (GNSS) RWY 10

Navdata will be updated effective AIRAC cycle 1907.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
14th May 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com