



10 May 2019

Cycle 1906-02

**FORWARD TO CHIEF PILOT IMMEDIATELY**

**\*\*\* Collins Aerospace Notice of J3, J4, and J5 EurAsiaPac Coverage Reduction \*\*\***

**To: Subscribers to the J3, J4, and J5 EAP East Navigation Databases  
Subscribers to the J3, J4, and J5 EAP West Navigation Databases**

**From: Flight Database Services Technical Support**

**SUBJECT: J3, J4, and J5 EAP East Coverage Change  
J3, J4, and J5 EAP West Coverage Change  
Cycle 1906 - Release Date: Friday, May 10, 2019**


**Overview**

Due to Flight Management System (FMS) memory limitations and the continual growth of the amount of data in the navigation database, Collins Aerospace will make a change to the J3, J4, and J5 EAP East and EAP West coverage regions.


**Detail**

As a result of the increase in the amount of navigation data, the coverage region of the J3, J4, and J5 EAP East and EAP West databases must be reduced so they can load into the FMS.

With the 1906 release, the updated J3-J5 EAP East region map is shown below.



With the 1906 release, the updated J3-J5 EAP West map is shown below.



## Future

Although our new regions provide room for anticipated growth, Collins Aerospace will continue to evaluate and adjust region size as necessary. Current coverage maps are located on the Collins Aerospace Flight Deck Content web page located at:

<https://www.rockwellcollins.com/Services-and-Support/Database-and-Software-Updates/Navigation-Databases/Coverage-Maps.aspx>

If you have questions regarding these regional coverage changes, please contact Collins Aerospace, Flight Database Services at [CollinsDatabaseTech@RockwellCollins.com](mailto:CollinsDatabaseTech@RockwellCollins.com)