

Navigation Database Addendum

CORRECTION to AIRAC 1905 – Issue 19
NOTAM P3075/19 effective 7th May 2019

ETHL Laupheim EDMM ED Germany

Runway RWY 27

DB does not reflect Threshold 27 with following temporary displaced coordinates: N48 13 11.94 / E009 54 59.88.

Navdata will be updated effective AIRAC cycle 1907.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
7th May 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com